



# technical bulletin

15



INFORMATION DRIVESHAFT HARDWARE

NUMBER 89.01


MODELS:

ALL GTV-6 AND MILANO VEHICLES

DATE

5/1/89

During assembly of the GTV-6 and Milano models of Alfa Romeo, the factory precision balances the driveshaft on the car. The balance of the driveshaft is adjusted by using different thickness nuts and/or two nuts on one bolt. (See Fig. 1)



1. Driveshaft mounting nuts

Fig. "1"

REMARKS Any questions? Call the Alfa Romeo Technical  
"HOT LINE"! 1-800-541-7093

PAGE

1 of 2

Technical Bulletin #89.01  
Group "15"  
May 1, 1989

Page Two

All hardware and driveshaft components must be refitted exactly as the factory assembled them.

Whenever removing or disconnecting the driveshaft from the vehicle mark the position of all mounting hardware and driveshaft components so that they can be returned to their original position to preserve driveshaft balance.

Sincerely,

ALFA ROMEO DISTRIBUTORS OF NORTH AMERICA  
Technical Services Department